Analysis & Dashboard Report

PDI GADDI

KOLKATA

Phone: +91 98366 12609
E-mail: support@pdigaddi.com

VOLKSWAGEN JETTA COMFORTLINE MT DIESEL



Analysis & Dashboard Report			
Registration State	West Bengal	Manf. Year & months	2011
Registration No	WB06F****	Fitness Status	Valid
RTO Name	Katwa	Fitness date	28 Jan 2011
Make	Volkswagen	Registration Year	25 Jan 2031
Model	Jetta	Road Tax Status	Valid
Variant	Comfortline	Road Tax Date	27 Jan 2031
Ownership No	3	Insurance Type	Third Party
Odometer	47729	Insurance Date	16 Apr 2027
RC Condition	Online	No Claim Bonus	N/A
RC Mismatch	No Mismatch	Engine/motor no	******
Hypo	N/A	Chassis No	WVWK101K4AA55****
Hypo Bank	N/A	Chassis No Status	Valid
Bank NOC Availability	N/A	Duplicate Key	Available
Interstate NOC	N/A	Party Peshi	Required
Interstate NOC Validity	N/A	Transmission	MT
Car Condition	Good	Car Colour	White
Fuel Type	Diesel	Car Accidental Status	**Non-Accidental**
CAR STRUCTURE			
Arpon RHS	Good	Arpon LHS	Good
Cowl Panel	Good	Firewall	Good
Headlight Support	Good	Bonnet	Repaint
Radiator Support	Good	Roof	Dent
Upper Cross Member	Good	Boot Floor	Good
Lower Cross Member	Good	Dickey / Boot Door	Repaint
Front Windshield	Scratch	Rear Windshield	Good
CAR EXTERIOR PANEL			
Front Bumper	Repaint	Rear Bumper	Repaint
RHS OVRM	Good	LHS OVRM	Good
Pillar A - RHS	Repaint	Pillar A - LHS	Repaint
Pillar B - RHS	Good	Pillar B - LHS	Good
Pillar C - RHS	Repaint	Pillar C - LHS	Repaint
RHS Fender	Repaint	LHS Fender	Repaint
RHS Front Door	Repaint	LHS Front Door	Repaint
RHS Rear Door	Repaint	LHS Rear Door	Repaint
RHS Quater Panel	Repaint	LHS Quater Panel	Repaint
RHS Running Board	Repaint Dent	LHS Running Board	Repaint Dent

CAR TYRES			
Wheels Type	Alloy Wheel	Wheel Condition	Scratch
RHS front tyre	80-100%	LHS front tyre	80-100%
RHS Rear tyre	80-100%	LHS rear tyre	80-100%
Tools	Not Available	Spare Tyre	80-100%
ENGINE			
Engine Condition	Good	Engine/motor Mounting	Good
Silencer	Good	catalytic converter	Good
Battery	Good	Back compression	Minor Available
Coolant	Good	Exhaust Smoke	Good
Engine Oil	Leakage	Clutch	Minor Spongy
Engine Dipstick	Good	Gear Shift	Good
STEERING & BRAKES			
Steering	Good	Suspension	Good
Brakes	Spongy	ABS	Available & Working
Front shock absorber	Good	Rear shock absorber	Good
Electricals & Interior			
Dashboard	Good	Steering Mounting control	Available & Working
Music system	Good	Sun Roof	Not Available
Sterio	Screen Touch	Leather Seats	Available & Working
Inbuilt Speaker	Good	Reverse Camera / Sensor	Available & Not Working
Exterior Speaker	Not Available	Instrument Cluster	Available & Working
Rear Defogger	Available	Cruise control	Not
GPS Navigation	Not Available	Power seat	Available & Working
Front Power Window	Available Not working	Rear Power Window	Available & Working
MIL light	Available Glowing	ABS light	Available Glowing
Roof carpet	Dirty	Rear wiper	Not Available
RHS Tail Lamp	Crack	LHS Tail Lamp	Available & Working
RHS Headlamp	Good	LHS Headlamp	Available & Working
RHS Fog Light	Good	LHS Fog Light	Available & Working
Airbags	Available & Working	AC Condition	Not working
No of Airbags	6	Climate Control	Available & Working

Remarks:- Lhs fogg lamp bezzel damage, brake pedal low, front lhs window switch not working, rhs indicator broken, wheel wrench not available, sear adjustment knob damage, ac compressor not working, abs light glowing, airbag light glowing, obd light glowing, ac vent adjustment knob not Available,



Front view



Rear View



Left side quater view




Right side quater view



Left side fender view



Right side fender view



Right Side



Left Side



ABS Padle



Odometer




Music syestem



Fuel lead



Steering Wheel



Under body



Roof



Spare tyre



Front Right Side Tyre




Rear Right Side Tyre




Front left Side Tyre



Rear Left Side Tyre



Chassis imprint



Chassis plate



Gear lever




Front door



Front Seat



Dashbord



Rear seat



Dickey floor



Roof carpet



Rear glass



Dickey door



Engine room



Battery



Front bumper



Front bumper



Right side fender



Right side ORVM



Right side font door



Right side rear door



Right side QTR panel



Right side runing panel



Right side Tail lamp



Rear bumper



Rear bumper



Left side tail lamp



Left side QTR panel



Left side rear door



Left side front door



Left side fender



Tail lamp



Seat cover



Seat cover



Hose pipe



Engine side

Disclaimer: This inspection summary report is compiled based on information provided to us including Dale documents, MMV, year, condition, odometer reading and external examination of the vehicle/components. The report will not tell you about hidden defects or those problems which cannot be identify ed on a visual inspection. This report provides information on the observed condition of the vehicle as on inspection date (31-10-2026) and Pdigaddi does neither guarantee nor take liability for the correctness or completeness thereof. Note: To check the genuinely of condition report. # The odometer reading is at the time of inspection of car, actual odometer reading might vary