Analysis & Dashboard Report

PDI GADDI

KOLKATA

Phone: +91 98366 12609
E-mail: support@pdigaddi.com

TATA SIERRA PURE PLUS PETROL MT




Analysis & Dashboard Report			
Registration State	N/A	Manf. Year & months	Sept-2026
Registration No	N/A	Fitness Status	N/A
RTO Name	N/A	Fitness date	N/A
Make	TATA	Registration Year	N/A
Model	SIERRA	Road Tax Status	N/A
Variant	PURE PLUS	Road Tax Date	N/A
Ownership No	0	Insurance Type	N/A
Odometer	27	Insurance Date	N/A
RC Condition	N/A	No Claim Bonus	N/A
RC Mismatch	N/A	Engine/motor no	****
Hypo	N/A	Chassis No	MAT876080TAJD****
Hypo Bank	N/A	Chassis No Status	Good
Bank NOC Availability	N/A	Duplicate Key	Available
Interstate NOC	N/A	Party Peshi	N/A
Interstate NOC Validity	N/A	Transmission	MT
Car Condition	Good	Car Colour	C BLACK
Fuel Type	Petrol	Car Accidental Status	Non-Accidental
CAR STRUCTURE			
Arpon RHS	Good	Arpon LHS	Good
Cowl Panel	Good	Firewall	Good
Headlight Support	Good	Bonnet	Good
Radiator Support	Good	Roof	Good
Upper Cross Member	Good	Boot Floor	Good
Lower Cross Member	Good	Dickey / Boot Door	Scratch
Front Windshield	Good	Rear Windshield	Good
CAR EXTERIOR PANEL			
Front Bumper	Good	Rear Bumper	Good
RHS OVRM	Good	LHS OVRM	Good
Pillar A - RHS	Good	Pillar A - LHS	Good
Pillar B - RHS	Good	Pillar B - LHS	Good
Pillar C - RHS	Good	Pillar C - LHS	Good
RHS Fender	Good	LHS Fender	Good
RHS Front Door	Good	LHS Front Door	Scratch
RHS Rear Door	Good	LHS Rear Door	Scratch
RHS Quater Panel	Good	LHS Quater Panel	Good
RHS Running Board	Good	LHS Running Board	Good

CAR TYRES			
Wheels Type	Alloy wheel	Wheel Condition	Good
RHS front tyre	Aug-2026	LHS front tyre	Aug-2026
RHS Rear tyre	Aug-2026	LHS rear tyre	Aug-2026
Tools	Available	Spare Tyre	Aug-2026
ENGINE			
Engine Condition	Good	Engine/motor Mounting	Good
Silencer	Good	catalytic converter	Available & Working
Battery	Good	Back compression	Not Available
Coolant	Good	Exhaust Smoke	Colourless
Engine Oil	Good	Clutch	Good
Engine Dipstick	Good	Gear Shift	Good
STEERING & BRAKES			
Steering	Good	Suspension	Good
Brakes	Good	ABS	Available & Working
Front shock absorber	Good	Rear shock absorber	Good
Electricals & Interior			
Dashboard	Good	Steering Mounting control	Available & Working
Music system	Available & Working	Sun Roof	Available & Working
Sterio	Screen Touch	Leather Seats	Available
Inbuilt Speaker	Available & Working	Reverse Camera / Sensor	Available & Working
Exterior Speaker	Not Available	Instrument Cluster	Available & Working
Rear Defogger	Available & Working	Cruise control	Available & Working
GPS Navigation	Not available	Power seat	Available & Working
Front Power Window	Available & Working	Rear Power Window	Available & Working
MIL light	Available & Working	ABS light	Available & Working
Roof carpet	Good	Rear wiper	Available & Working
RHS Tail Lamp	Available & Working	LHS Tail Lamp	Available & Working
RHS Headlamp	Available & Working	LHS Headlamp	Available & Working
RHS Fog Light	Not available	LHS Fog Light	Not available
Airbags	Available & Working	AC Condition	Available & Working
No of Airbags	6	Climate Control	Available & Working
Remarks	dickey door hinges rust, left side boot door and dickey door scratch, Bonnet leaver need to be fixed. Engine sound - https://youtu.be/fiZmDi9EZCQ		



Front view



Rear View



Left side quater view



Right side quater view



Dickey boot



Right side fender view



Right Side



Left Side




ABS Padle



Odometer



Music syestem




Revers camera



Steering Wheel



Under body



Roof




spare tyre



Front Right Side Tyre




Rear Right Side Tyre




Front left Side Tyre



Rear Left Side Tyre



Chassis punch



Chassis plate



Gear lever




Dickey boot



Front Seat



Dashboard




Rear seat



Fuel/charging lead




Front door



Rear glass




Engine room/Motor room



Battery



Front glass




Dickey door hinges



Bonnet lead



Left side front door



Left side rear door



Dickey door



Dickey door



Dickey door



Dickey door



Paint value

Disclaimer: This inspection summary report is compiled based on information provided to us including Dale documents, MMV, year, condition, odometer reading and external examination of the vehicle/components. The report will not tell you about hidden defects or those problems which cannot be identify ed on a visual inspection. This report provides information on the observed condition of the vehicle as on inspection date (31-10-2026) and Pdigaddi does neither guarantee nor take liability for the correctness or completeness thereof. Note: To check the genuinely of condition report. # The odometer reading is at the time of inspection of car, actual odometer reading might vary